

AMENDMENTS TO THE SPECIFICATION

Please add the following new paragraph after paragraph [0022]

[0022.1] Figure 9 is a partial perspective view of coaxial clock line 31 showing how second plate 46 is sandwiched between inner conductor 33 and first plate 45.